

BAUER SUBSIDIARIES
 BAUER PARTNERS & DEALERS
 END USER
 REPLACEMENT PROMPTLY
 REPLACEMENT GRADUALLY



Quality. Our DNA

BREATHING AIR CHECK CHART

AEROTEST / B-DETECTION

CUSTOMER

Basacuda

INSPECTOR

Init: F.C.
 BAY Kompressor Aps
 Fuglebækvej 4A
 DK-2770 Kastrup

SERIAL NO.: 10-104207
 MANUFACTURER: Bauer
 PRESSURE: 220
 ANALYSIS of Pressure Vessel:
 ANALYSIS of compressor station:

TYPE: J11-B
 DATE: 2010
 NITROX:
 AEROTEST:
 B-DETECTION:

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m ³	<u>10</u> mg/m ³	OK / FAILED
CARBON MONOXIDE	≤ 5ml/m ³ (ppm)	<u>25</u> ml/m ³ (ppm)	OK / FAILED
CARBON DIOXIDE	≤ 500ml/m ³ (ppm)	<u>2250</u> ml/m ³ (ppm)	OK / FAILED
OIL / VOC	≤ 0.5mg/m ³ (AIR) ≤ 0.1mg/m ³ (NITROX)	<u>201</u> mg/m ³	OK / FAILED
NITROUS GASES (NOx)	≤ 5ml/m ³ (ppm)	<u>25</u> ml/m ³ (ppm)	OK / FAILED
OXYGEN	21% ±1% %	OK / FAILED

REMARKS:

19-3-19

DATE:

OK ✓
F.C.

INSPECTOR

CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH

Stäblistr. 8
 81477 Munich
 Tel. +49 (0) 89 78049-0
 Fax +49 (0) 89 78049-167
 info@bauer-kompressoren.de
 www.bauer-kompressoren.de



CHECKLIST CLEAN AIR
 # 03.2018