

BAUER SUBSIDIARIES
 BAUER PARTNERS & DEALERS
 END USER
 REPLACEMENT PROMPTLY
 REPLACEMENT GRADUALLY



BREATHING AIR CHECK CHART

AEROTEST / B-DETECTION

CUSTOMER

INSPECTOR

Baracuda

Init: F.C

BAY Kompressor ApS

Fuglebækvej 4A

DK-2770 Kastrup

SERIAL NO.: Block nr 4/215/2

TYPE: Capitane

MANUFACTURER: Bauer

YEAR: 2

PRESSURE: 210 bar

NITROX:

ANALYSIS of Pressure Vessel:

AEROTEST:

ANALYSIS of compressor station:

B-DETECTION

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m ³ <u>0</u> mg/m ³	<u>OK</u> / FAILED
CARBON MONOXIDE	≤ 5ml/m ³ (ppm) <u><5</u> ml/m ³ (ppm)	<u>OK</u> / FAILED
CARBON DIOXIDE	≤ 500ml/m ³ (ppm) <u><150</u> ml/m ³ (ppm)	<u>OK</u> / FAILED
OIL / VOC	≤ 0.5mg/m ³ (AIR) ≤ 0.1mg/m ³ (NITROX) <u><0.1</u> mg/m ³	<u>OK</u> / FAILED
NITROUS GASES (NOx)	≤ 5ml/m ³ (ppm) <u><5</u> ml/m ³ (ppm)	<u>OK</u> / FAILED
OXYGEN	21% ±1% %	OK / FAILED

REMARKS:

OK ✓

02-03-22
 DATE:

Flemming Hjorth Christiansen
 INSPECTOR

CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH
 Stäblistr. 8
 81477 Munich
 Tel. +49 (0) 89 78049-0
 Fax +49 (0) 89 78049-167
 info@bauer-kompressoren.de
 www.bauer-kompressoren.de



CHECKLIST CLEAN AIR
 # 03.2018