BAUER SUBSIDIARIES
BAUER PARTNERS & DEALERS
END USER
REPLACEMENT PROMPTLY
REPLACEMENT GRADUALLY

BAUER KOMPRESSOREN
Quality. Our DNA

BREATHING AIR CHECK CHART

AEROTEST / B-DETECTION

CUSTOMER

Baracuda Dykkerklub-Ballerup

INSPECTOR

Init: S.A

BAY Kompressor ApS
Fuglebækvej 4A
DK-2770 Kastrup

SERIAL NO.: Blok nr. 4/2515/2
MANUFACTURER: Bauer
PRESSURE: 7200 Bar

TYPE: Capitano - E
YEAR:

ANALYSIS of Pressure Vessel: ☐
ANALYSIS of compressor station: ☒

NITROX: ☐
AEROTEST: ☒
B-DETECTION ☐

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m³	≤ 5 mg/m³	OK / ~~FAILED~~
CARBON MONOXIDE	≤ 5ml/m³ (ppm)	≤ 5 ml/m³ (ppm)	OK / ~~FAILED~~
CARBON DIOXIDE	≤ 500ml/m³ (ppm)	≤ 100 ml/m³ (ppm)	OK / ~~FAILED~~
OIL / VOC	≤ 0.5mg/m³ (AIR) ≤ 0.1mg/m³ (NITROX)	≤ 0.1 mg/m³	OK / ~~FAILED~~
NITROUS GASES (NOx)	≤ 5ml/m³ (ppm)	≤ 5 ml/m³ (ppm)	OK / ~~FAILED~~
OXYGEN	~~21% ±1%~~	~~%~~	~~OK~~ / ~~FAILED~~

REMARKS:

4/4-2024
DATE:

Søren Andersen
INSPECTOR

CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH
Stäblistr. 8
81477 Munich
Tel. +49 (0) 89 78049-0
Fax +49 (0) 89 78049-167
info@bauer-kompressoren.de
www.bauer-kompressoren.de

TÜV SÜD ISO 9001