

BAUER SUBSIDIARIES
 BAUER PARTNERS & DEALERS
 END USER
 REPLACEMENT PROMPTLY
 REPLACEMENT GRADUALLY



BREATHING AIR CHECK CHART

AEROTEST / B-DETECTION

CUSTOMER

INSPECTOR

Baracuda

Init:..... *F.C*

BAY Kompressor ApS
 Fuglebækvej 4A
 DK-2770 Kastrup

SERIAL NO.: *Dok nr. 4/215/2*

TYPE: *Capitono*

MANUFACTURER: *Bauer*

YEAR: *? Goerne*

PRESSURE:

NITROX:

ANALYSIS of Pressure Vessel:

AEROTEST:

ANALYSIS of compressor station:

B-DETECTION

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m ³	<i>5</i> mg/m ³	<input checked="" type="checkbox"/> OK / FAILED
CARBON MONOXIDE	≤ 5ml/m ³ (ppm)	<i>25</i> ml/m ³ (ppm)	<input checked="" type="checkbox"/> OK / FAILED
CARBON DIOXIDE	≤ 500ml/m ³ (ppm)	<i>250</i> ml/m ³ (ppm)	<input checked="" type="checkbox"/> OK / FAILED
OIL / VOC	≤ 0.5mg/m ³ (AIR) ≤ 0.1mg/m ³ (NITROX)	<i>201</i> mg/m ³	<input checked="" type="checkbox"/> OK / FAILED
NITROUS GASES (NOx)	≤ 5ml/m ³ (ppm)	<i>25</i> ml/m ³ (ppm)	<input checked="" type="checkbox"/> OK / FAILED
OXYGEN	21% ±1%%	OK / FAILED

REMARKS:

OK ✓

14-04-21
 DATE:

Flemming Christiansen
 INSPECTOR

.....
 CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH
 Stäblistr. 8
 81477 Munich
 Tel. +49 (0) 89 78049-0
 Fax +49 (0) 89 78049-167
 info@bauer-kompressoren.de
 www.bauer-kompressoren.de



CHECKLIST CLEAN AIR
 # 03.2018