BAUER SUBSIDIARIES ■
BAUER PARTNERS & DEALERS ■
END USER ■
REPLACEMENT PROMPTLY ☐
REPLACEMENT GRADUALLY ■

BAUER KOMPRESSOREN
Quality. Our DNA

BREATHING AIR CHECK CHART
AEROTEST / B-DETECTION

CUSTOMER

BARACUDA
Ballerup Idrætsby 28B 5TH
2750 Ballerup

INSPECTOR

Init: JR

BAY Kompressor Aps
Fuglebækvej 4A
DK-2770 Kastrup

SERIAL NO.: 10-104207
MANUFACTURER: BAUER
PRESSURE:
ANALYSIS of Pressure Vessel: ☒
ANALYSIS of compressor station: ☐

TYPE: CAPITANO 140
YEAR: 2002
NITROX: ☐
AEROTEST: ☒
B-DETECTION ☐

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m³	< 10 mg/m³	OK / FAILED
CARBON MONOXIDE	≤ 5ml/m³ (ppm)	< 5 ml/m³ (ppm)	OK / FAILED
CARBON DIOXIDE	≤ 500ml/m³ (ppm)	< 100 ml/m³ (ppm)	OK / FAILED
OIL / VOC	≤ 0.5mg/m³ (AIR) ≤ 0.1mg/m³ (NITROX)	< 0,1 mg/m³	OK / FAILED
NITROUS GASES (NOx)	≤ 5ml/m³ (ppm)	< 0,5 ml/m³ (ppm)	OK / FAILED
OXYGEN	21% ±1%	20,8 %	OK / FAILED

REMARKS:

16.03.26
DATE:

INSPECTOR

CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH
Stäblistr. 8
81477 Munich
Tel. +49 (0) 89 78049-0
Fax +49 (0) 89 78049-167
info@bauer-kompressoren.de
www.bauer-kompressoren.de

TÜV SÜD ISO 9001