

BAUER SUBSIDIARIES
 BAUER PARTNERS & DEALERS
 END USER
 REPLACEMENT PROMPTLY
 REPLACEMENT GRADUALLY



BREATHING AIR CHECK CHART

AEROTEST / B-DETECTION

CUSTOMER

INSPECTOR

Basacuda

Init:..... *F.C*

BAY Kompressor ApS
 Fuglebækvej 4A
 DK-2770 Kastrup

SERIAL NO.: .. *5206-2308* ..
 MANUFACTURER: .. *Bauer* ..
 PRESSURE: .. *225 bar* ..
 ANALYSIS of Pressure Vessel:
 ANALYSIS of compressor station:

TYPE: .. *Marina 250 E* ..
 YEAR: .. *2006* ..
 NITROX:
 AEROTEST:
 B-DETECTION

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m ³	... <i>15</i> ... mg/m ³	<input checked="" type="checkbox"/> OK / FAILED
CARBON MONOXIDE	≤ 5ml/m ³ (ppm)	... <i>25</i> ... ml/m ³ (ppm)	<input checked="" type="checkbox"/> OK / FAILED
CARBON DIOXIDE	≤ 500ml/m ³ (ppm)	... <i>250</i> ... ml/m ³ (ppm)	<input checked="" type="checkbox"/> OK / FAILED
OIL / VOC	≤ 0.5mg/m ³ (AIR) ≤ 0.1mg/m ³ (NITROX)	... <i>0.1</i> ... mg/m ³	<input checked="" type="checkbox"/> OK / FAILED
NITROUS GASES (NOx)	≤ 5ml/m ³ (ppm)	... <i>25</i> ... ml/m ³ (ppm)	<input checked="" type="checkbox"/> OK / FAILED
OXYGEN	21% ±1% %	<input checked="" type="checkbox"/> OK / FAILED

REMARKS:

OK

14-01-21
 DATE:

.....
 Flemming Christiansen
 INSPECTOR

.....
 CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH
 Stäblstr. 8
 81477 Munich
 Tel. +49 (0) 89 78049-0
 Fax +49 (0) 89 78049-167
 info@bauer-kompressoren.de
 www.bauer-kompressoren.de



CHECKLIST CLEAN AIR
 # 03.2018