

BAUER SUBSIDIARIES
 BAUER PARTNERS & DEALERS
 END USER
 REPLACEMENT PROMPTLY
 REPLACEMENT GRADUALLY



Quality. Our DNA

BREATHING AIR CHECK CHART

AEROTEST / B-DETECTION

CUSTOMER

Baracuda

INSPECTOR

Init: F.C

 BAY Kompressor Aps
 Fuglebækvej 4A
 DK-2770 Kastrup

SERIAL NO.: 5206-2308
 MANUFACTURER: Bauer
 PRESSURE: 320
 ANALYSIS of Pressure Vessel:
 ANALYSIS of compressor station:

TYPE: Mariner 250E
 DATE: 2006
 NITROX:
 AEROTEST:
 B-DETECTION:

| TEST MEDIUM | TARGET | VALUE | RESULT |
|----------------------------------|---|---|------------------------|
| WATER | ≤ 25mg/m ³ | ... <u>10</u> ... mg/m ³ | OK / FAILED |
| CARBON MONOXIDE | ≤ 5ml/m ³ (ppm) | ... <u>25</u> ... ml/m ³ (ppm) | OK / FAILED |
| CARBON DIOXIDE | ≤ 500ml/m ³ (ppm) | ... <u>2350</u> ... ml/m ³ (ppm) | OK / FAILED |
| OIL / VOC | ≤ 0.5mg/m ³ (AIR) ≤ 0.1mg/m ³ (NITROX) | ... <u>203</u> ... mg/m ³ | OK / FAILED |
| NITROUS GASES (NO _x) | ≤ 5ml/m ³ (ppm) | ... <u>25</u> ... ml/m ³ (ppm) | OK / FAILED |
| OXYGEN | 21% ±1% | % | OK / FAILED |

REMARKS:

OK ✓
Fugle Aps

19-3-19
 DATE:

INSPECTOR

CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH

Stäblistr. 8
 81477 Munich

Tel. +49 (0) 89 78049-0
 Fax +49 (0) 89 78049-167

info@bauer-kompressoren.de
 www.bauer-kompressoren.de



CHECKLIST CLEAN AIR
 # 03.2018