

BAUER SUBSIDIARIES  
 BAUER PARTNERS & DEALERS  
 END USER  
 REPLACEMENT PROMPTLY  
 REPLACEMENT GRADUALLY



# BREATHING AIR CHECK CHART

## AEROTEST / B-DETECTION

CUSTOMER

INSPECTOR

Baracuda  
 .....  
 .....  
 .....

Init: F.C  
 .....

BAY Kompressor ApS  
 Fuglebækvej 4A  
 DK-2770 Kastrup

SERIAL NO.: 5206-2308

TYPE: Mexiner 250E

MANUFACTURER: Bauer

YEAR: 2006

PRESSURE: 370 bar

ANALYSIS of Pressure Vessel:

NITROX:

ANALYSIS of compressor station:

AEROTEST:

B-DETECTION

TEST MEDIUM	TARGET	VALUE	RESULT
WATER	≤ 25mg/m <sup>3</sup>	<u>&lt; 15</u> mg/m <sup>3</sup>	<u>OK</u> / FAILED
CARBON MONOXIDE	≤ 5ml/m <sup>3</sup> (ppm)	<u>&lt; 5</u> ml/m <sup>3</sup> (ppm)	<u>OK</u> / FAILED
CARBON DIOXIDE	≤ 500ml/m <sup>3</sup> (ppm)	<u>&lt; 450</u> ml/m <sup>3</sup> (ppm)	<u>OK</u> / FAILED
OIL / VOC	≤ 0.5mg/m <sup>3</sup> (AIR) ≤ 0.1mg/m <sup>3</sup> (NITROX)	<u>2011</u> mg/m <sup>3</sup>	<u>OK</u> / FAILED
NITROUS GASES (NOx)	≤ 5ml/m <sup>3</sup> (ppm)	<u>&lt; 5</u> ml/m <sup>3</sup> (ppm)	<u>OK</u> / FAILED
OXYGEN	<del>21% ± 1%</del>	<del>.....</del> %	<del>OK</del> / FAILED

REMARKS:

OK

20-02-23  
 DATE:

Flemming Hjorth Christiansen  
 INSPECTOR

CUSTOMER

Test has been carried out according to DIN EN 12021:2014.

BAUER KOMPRESSOREN GmbH

Stäblistr. 8  
 81477 Munich

Tel. +49 (0) 89 78049-0  
 : +49 (0) 89 78049-167

info@bauer-kompressoren.de  
 www.bauer-kompressoren.de



CHECKLIST CLEAN AIR  
 # 03.2016